# South County Property Inspections

**Propery Inspection Report** 



2673 Milton, Fullerton, CA. 92831
Inspection prepared for: Ketchum University
Date of Inspection: 3/5/2015 Time: 10:00 A.M
Age of Home: 36 Years Old Size: 1, 202 Square Feet per Assessor
Weather: Recent Rain

Inspector: Dennis Bishop License #06120902 NACHI 3451 Calle La Veta, San Clemente, CA 92672

Phone: 949.322.6489

Email: dennis@SCPropertyInspections.com www.SCPropertyInspections.com

# SOUTH COUNTY PROPERTY INSPECTIONS

Residential ~ Commercial

Making sure your dream castle is on a solid foundation"

On this page you will find, in RED, a brief summary of any CRITICAL concerns of the inspection, as they relate to Safety and Function. Examples would be bare electrical wires, or active drain leaks. The complete list of items noted is found throughout the body of the report, including Normal Maintenance items. Be sure to read your entire report!

For your safety and liability, we recommend that you hire only licensed contractors when having any work done. If the living area has been remodeled or part of an addition, we recommend that you verify the permit and certificate of occupancy. This is important because our inspection does not tacitly approve, endorse, or guarantee the integrity of any work that was done without a permit, and latent defects could exist.

Depending upon your needs and those who will be on this property, items listed in the body of the report may also be a concern for you; be sure to read your Inspection Report in its entirety.

Note: If there are no comments in RED below, there were no CRITICAL system or safety concerns with this property at the time of inspection.

# Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed &bonded trade professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

South County Property Inspections appreciates the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire

closing process.

Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific noncode, non-cosmetic concerns that the inspector feels may need further investigation or repair. For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

Master Bedroom		
Page 6 Item: 10	Ceiling Condition	<ul> <li>Small stains noted on the ceiling. They tested dry at the time of the inspection.</li> </ul>
Kitchen	Control (N. 1984) No. 1 They to the first on the control	
Page 14 Item: 8	Oven & Range	<ul> <li>Anti-Tip devises became a UL (Underwriters Laboratories) safety standard requirement in 1991.</li> </ul>
Roof		
Page 24 Item: 7	Gutter	Gutter leak noted. Potential hazard repairs recommended.
Grounds	general de la companya de la company	
Page 29 Item: 6	Stairs & Handrail	<ul> <li>The metal railing showing areas of rust. Refinish, prime, and paint as needed.</li> </ul>
Page 31 Item: 16	Patio and Porch Condition	Evidence of water intrusion on the starter board on the balcony area.

# **Inspection Details**

1. Attendance

In Attendance: Client present, Fully Participated

2. Home Type

Home Type: Attached • Condominium/Townhouse

3. Occupancy

Occupancy: Vacant • The utilities were on at the time of inspection.

### **Interior Areas**

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should

be o	cons	ulted	if yo	ou wo	ould like further testing.
1. C	abir	ets			[2] 그리는 [2] 등에 가는 경기 되는 이어 그는 얼룩하는 이어는 그는 것이다. 그렇지다.
Good	Fair	Poor	N/A	None	n Observations:
X		ļ		<u> </u>	Appeared functional and in satisfactory condition, at time of inspection.
,,-		g Fa	ns		
Good	Fair	Poor	N/A	None	n Observations:
X					Operated normally when tested, at time of inspection.
3. C	lose	ts			
Good	Fair	Poor	N/A	None	n Observations:
X					• The closet is in serviceable condition.
4. C	)oor	Bell			British didentila a la
Good	Fair	Poor	N/A	None	Observations:
X					Operated normally when tested.
5. C	)oors				
Good	Fair	Poor	N/A	None	Observations:
X					Hollow wood doors.
6. E	lecti	ical			and the second of the second o
Good	Fair	Poor	N/A	None	n Observations:
X					• The majority of grounded receptacles , were tested and found to be wired
		<u> </u>		•	correctly.
		e De			
Good	Fair	Poor	N/A	None	Observations:
X				1	• **SMOKE DETECTORS**
					Operated when tested
		& H			
Good	Fair	Poor	N/A	None	Observations:
X	<u> </u>				Wrought iron stair railings noted.
		ow C		tion	
Good	Fair	Poor	N/A	None	Materials: Aluminum framed sliding window noted.
X					Observations:
					• Operated windows appeared functional, at time of inspection

#### Master Bedroom

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and

normal operation. Per inspector will not move	rsonal items in the bedroom personal items.	om may prevent all	areas to be ins	spected as the
1. Locations				
	Locations: Master#1			
2. Ceiling Fans				
Good Fair Poor N/A None	7 Observations:			
3. Closets				
Good Fair Poor N/A None	Observations: The closet is in servic	eable condition.		
4. Doors				
Good Fair Poor N/A None	Observations: - Hollow wood doors.			
5. Electrical				
Good Fair Poor N/A None	Observations: The majority of ground correctly.	ded receptacles , w	ere tested and	found to be wired
6. Floor Condition		A second of the		
Good Fair Poor N/A None	Flooring Types: Carpet	is noted.		
7. Smoke Detectors				
Good Fair Poor N/A None	Observations:  • **Smoke Detectors**			
	· The smoke detectors	operated during the	inspection.	
8. Wall Condition  Good Fair Poor N/A None				
X X	Materials: Drywall walls	noted.		
9. Window Condition				
X	7			
40 Calling Candition				

# 10. Ceiling Condition

Good	Fair	Poor	N/A	None	المملم والمسائلين المسام ومراجع والمسام والمسامل
					Materials: There are drywall ceilings noted.
	X				Observations:

· Small stains noted on the ceiling. They tested dry at the time of the inspection.





Small stains noted on the ceiling. They tested dry at the time of the inspection.

Small stains noted on the ceiling. They tested dry at the time of the inspection.

### 11. Patio Doors

X Poor N/A None

Observations:

• \*\*Sliding Patio Doors\*\*

• The sliding patio door was functional during the inspection.

# 12. Screen Doors

Good	rair	Poor	N/A	None
Х				

Observations:

Sliding door screen is functional.

#### Master Bathroom

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

inspector will identiful problems within the	fy as many issues as possible but some problems may be undetectable due to example walls or under the flooring.
1. Locations	
	Locations: Master Bathroom
2. Cabinets	
Good Fair Poor N/A N	Observations:  • Appeared functional and in satisfactory condition, at time of inspection.
3. Ceiling Condition	n – – – – – – – – – – – – – – – – – – –
Good Fair Poor N/A N	Materials: There are drywall ceilings noted.
4. Counters  Good Fair Poor N/A N	None
X	Observations:  • Solid Surface tops noted.  • There is normal wear noted for the age of the counter tops.
5. Doors	
Good Fair Poor N/A N	Observations:  • No major system safety or function concerns noted at time of inspection.
6. Electrical	
Good Fair Poor N/A N	Observations:  • No major system safety or function concerns noted at time of inspection.
7. GFCI Good Fair Poor N/A N	
X Fair Poor N/A N	Observations:  • GFCI in place and operational
	None X
9. Floor Condition	None Materials: Ceramic tile is noted.

# 10. Heating

X |

Х	 		Observations:  • Central heating and cooling noted in this room. At the time of the
		L	inspection, all appeared to be functioning and in serviceable condition.

		OFS	

Good	Fair	Poor	N/A	None
V				
🔨				

# 12. Plumbing

Good	Fair	Poor	N/A	None
Х				

### 13. Showers

Good	Fair	Poor	N/A	None
Х				

Observations:

- \*\*SHOWER BASE\*\*
- functional

# 14. Shower Walls

Good	Fair	Poor	N/A	None
Х				

Observations:


- \*\*MATERIALS\*\*
- · Ceramic tile noted.

# 15. Bath Tubs

Good	Fair	Poor	N/A	None
	Х			

Observations:
• Tub

- · Stopper is missing.



Stopper is missing.

# 16. Enclosure

None	N/A	Poor	Fair	Good
I V I		l 1		
1 ^ 1		1 1		

Observations:

Curtain present at the shower enclosure.

# 17. Sinks

Good	Fair	Poor	N/A	None
X				

# 18. Toilets

Good	Fair	Poor	N/A	Non
X				

Observations:

• Observed as functional and in good visual condition.

C 4 L	C		Inspections
$\sim$ ound	$\mathbf{c}$		insperions
Oddii	Obuilty	1 TOPCITY	mopeodono

2673 Milton, Fullerton, CA.

1	g	W	/in	do	w	C	าท	diti	on
1	σ.	•	,,,,,,	u	,,,	$\sim$	<i>7</i> 11	uiu	VI I

	<u>oa</u>	Fair	Poor	N/A	None	
						Materia
>	(					Observ

als: Aluminum framed sliding window noted.

Observations:

• Operated windows appeared functional, at time of inspection

	Guest Bedroom
1. Locations	
Aleksan and a second	Locations: Guest#2
2. Ceiling Fans  Good Fair Poor N/A None  X	Observations: • None present.
3, Closets Good Fair Poor N/A None X	Observations:  • The closet is in serviceable condition.
4. Doors Good Fair Poor N/A None X	Observations: • Hollow wood doors.
5. Electrical  Good Fair Poor N/A None  X	Observations:  • The majority of grounded receptacles , were tested and found to be wired correctly.
6. Floor Condition  Good Fair Poor N/A None  X	Flooring Types: Carpet is noted.
7. Smoke Detectors  Good Fair Poor N/A None  X	Observations:  • **Smoke Detectors**  • The smoke detectors operated during the inspection.
8. Wall Condition  Good Fair Poor N/A None  X	Materials: Drywall walls noted.
9. Window Condition Good Fair Poor N/A None X	Materials: Aluminum framed sliding window noted.
10. Ceiling Condition Good Fair Poor N/A None X	Materials: There are drywall ceilings noted.
11. Patio Doors Good Fair Poor N/A None X	
12. Screen Doors Good Fair Poor N/A None X	

# **Guest Bathroom**

1.	Locat	tions
----	-------	-------

Locations: Guest bathroom

#### 2. Cabinets

Good	Fair	Poor	N/A	None
Х				

Observations:

• Appeared functional and in satisfactory condition, at time of inspection.

# 3. Ceiling Condition

Good	Fair	Poor	N/A	None
Х				

Materials: There are drywall ceilings noted.

### 4. Counters

Good	Fair	Poor	N/A	None
Х				

Observations:

- Solid Surface tops noted.
- There is normal wear noted for the age of the counter tops.

# 5. Doors

Good	Fair	Poor	N/A	None
X				

Observations:

• No major system safety or function concerns noted at time of inspection.

# 6. Electrical

Good	Fair	Poor	N/A	None
Х				

Observations:

• No major system safety or function concerns noted at time of inspection.

# 7. GFCI

Good	Fair	Poor	N/A_	None
X				

ן Observations:

GFCI in place and operational

### 8. Exhaust Fan

Good	Fair	Poor	N/A	None
Х				

Observations:

• The bath fan was operated and no issues were found.

#### 9. Floor Condition

Good	Fair	Poor	N/A	None
	_			
X				l I

Materials: Ceramic tile is noted.

### 10. Heating

Good	Fair	Poor	N/A	None
Х				

Observations:

• Central heating and cooling noted in this room. At the time of the inspection, all appeared to be functioning and in serviceable condition.

#### 11. Mirrors

Good	Fair	Poor	N/A	None
Х				

#### 12. Plumbing

		_		
Good	Fair	Poor	N/A	None
X	l	l	l	l

South County Property Inspections	2673 Milton, Fullerton, CA
13. Showers    X     Display   Observations:   **SHOWER BASE**   • functional	
14. Shower Walls  Good Fair Poor N/A None  Observations:  **MATERIALS**  • Ceramic tile noted.	
15. Bath Tubs  Good Fair Poor N/A None  X	
16. Enclosure    Sood   Fair   Poor   N/A   None   Observations:   Y	nctional at the time of the inspection.
17. Sinks  Good Fair Poor N/A None  X	
18. Toilets  Good Fair Poor N/A None  Observations:  Observed as functional and in	
19. Window Condition  Good Fair Poor N/A None  X	

	Kitchen
The kitchen is used	d for food preparation and often for entertainment. Kitchens typically include a sink and other appliances.
1, Cabinets	onn and outer appliances.
Good Fair Poor N/A	Observations:  • Appeared functional and in satisfactory condition, at time of inspection.
2. Counters	
Good Fair Poor N/A	Observations:  Tile counter tops noted.
3. Dishwasher	
Good Fair Poor N/A	Observations:  operated
4. Doors	
Good Fair Poor N/A	X None
5. Garbage Dispos	al
Good Fair Poor N/A	Observations: Operated - appeared functional at time of inspection.
6. Microwave	
Good Fair Poor N/A	None
7. Cook top conditi	lon: None ☐ Observations:
X	Gas cook top noted.     The burners did operate properly when tested.
8. Oven & Range	
Good Fair Poor N/A	Observations:
	<ul> <li>Oven: gas burners</li> <li>Oven(s) operated when tested.</li> <li>Anti-Tip devises became a UL (Underwriters Laboratories) safety standard requirement in 1991.</li> </ul>
9. Sinks	
X Poor N/A	Observations:  • Kitchen has a Stainless steel - under mounted sink
10. Drinking Fount	ain
Good Fair Poor N/A	Observations:  X • There was no drinking fountain present in this kitchen.

South County Proper	ty Inspections 2673 Milton, Fullerton, C
11. Spray Wand	
Good Fair Poor N/A N	Observations: The spray wand was operated and was functional.
12. Vent Condition	
Good Fair Poor N/A N	Materials: Recirculating
13. Window Condit	27.46.29.77%
X Poor N/A N	Materials: Aluminum framed sliding window noted. Observations: Operated windows appeared functional, at time of inspection
14, Floor Condition	
Good Fair Poor N/A N	Materials: Floating laminate type flooring noted.
15. Plumbing  Good Fair Poor N/A N	one
X	
16. Ceiling Condition	
X	Materials: There are drywall ceilings noted.
17. Electrical  Good Fair Poor N/A N	One
x	Observations:  No major system safety or function concerns noted at time of inspection.
18. GFCI Good Fair Poor N/A N	one
x	Observations: GFCI in place and operational
19. Wall Condition  Good Fair Poor N/A N	One
X X X	Materials: Drywall walls noted.

od Fa	imbing		one						
	<u> </u>		CONTROL OF State States State & State			and the second s	eco disentationen intervisionen intervisione	proving the state of the complete with the	i da karangan sa
3. <b>W</b> a od Fa <		ndition	<sup>∞ne</sup> ∏Materia	ıls: Drywa	ıll walls not	ed.			
I, Ce	iling C	ondițio	n 🔻						
od Fa				ls: There	are drywal	l ceilings no	ted.		
5. Do		N/A N	one						4
			<b>X</b>						

#### Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed C-20 HVAC contractor..

	44.2		37402 -		
4	1 1 2 100	1	<b>^</b>		L:
1.	Hea	Ter I	or	ıaı	non

Good	Fair	Poor	N/A	None
Х				

Materials: Location: • The furnace is located in the hall closet

Materials: Gas fired forced hot air

Observations:

• Fuel Furnace: Last service date is over one year ago, or is unable to be determined. Although this unit appears to be operating properly from controls, there are areas which cannot be seen without specialized equipment and training. One such area is the combustion chamber / heat exchanger where cold air blows across the "fire box", becoming the hot air that circulates throughout your home. During the life span of any furnace, this metal wall may develop a crack or a broken weld, allowing carbon monoxide to circulate throughout the home. This is why furnace specialists recommend a complete inspection annually; consider having unit inspected by certified HVAC technician.

# 2. Heater Base

GUUG	r an	 187	110110
V			
^			

Observations:

• The heater base appears to be functional.

#### 3. Enclosure

	427	COLD ALL .		
Good	Fair	Poor	N/A	None
Х				

# 4. Venting

Good	Fair	Poor	N/A	None
Х				

Observations:

- \*\*VENTING MATERIALS\*\*
- Metal single wall chimney vent pipe noted.

#### 5. Gas Valves

Good	Fair	Poor	N/A	None
.,				
X		1 1		

Observations:

• Gas shut off valves were present and functional.

#### 6. Refrigerant Lines

G000	rair	Poor	N/A	NOUE
Х				

Observations:

No defects found.

#### 7. AC Compress Condition

Good	Fair	Poor	N/A	None
^				

Compressor Type: electric

Location: The compressor is located on the roof.

. Air Supply								
		bservations: The return ai		ctem anne:	ere to he fi	ınctional	TO THE PART OF	
		IIIC IGium an	I Supply Sy	stem appea	113 IO DE 10	Mclionai.		**************************************
		bservations:						
<u> </u>	e ezenti vi elenintalliki helenhi.	The return ai	r supply sy	stem appea	ars to be fu	ınctional.		
O, Filters	N/A None Lo	ocation: Loca	ited inside	heater cabi	net.			
1. Thermosta	NI/A Non-	bservations:				25		3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
x		Location: Din Digital - progr Functional at Thermostats	ing area rammable the time of	lype. f inspection	ı. Əlibration c	er timed fun	ctions	
		monnosaus	uio iiot o	201.04 101 U	Alloradori C	i timog ig	ouono.	

Χ

Χ

11. Strapping

Observations:

Observations:

Appears to be in satisfactory condition.

• The water heater is strapped.


1. Roof Condition	Garage
* 12.2.2.2.2. <del>*</del> = 11.3.3.2.2.1	Materials: Common area of home owners association. • Observed from the ground with 8X56 field glasses. • Roof was visually inspected from accessible points on the interior and/or exterior. If a roof is too high, is too steep, is wet, or is composed of materials which can be damaged if walked upon, the roof is not mounted. Therefore, client is advised that this is a limited review and a licensed roofer should be contacted if a more detailed report is desired.
2. Walls	
Good Fair Poor N/A N	Observations:  • Appeared satisfactory, at time of inspection.
3. Anchor Bolts	
Good Fair Poor N/A N	Observations: The anchor bolts were not visible, obscured by drywall.
4. Floor Condition	
Good Fair Poor N/A N	Materials: Bare concrete floors noted.
5. Rafters & Ceiling	
Good Fair Poor N/A N	Observations:  Not visible to determine.
6. Electrical	
Good Fair Poor N/A N	Observations:  • The majority of grounded receptacles , were tested and found to be wired correctly.
7. GFCI Good Fair Poor N/A N	lone
	x
8. 240 Volt	
	Observations:  There are no 240 volt outlets visible in this room.
9. Exterior Door	
	X One
10. Fire Door	
	Observations:
[X	Operated When Tested

South County Prope	erty Inspections	2673 Milton, Fullerton, C.
11. Garage Door	Condition	
X Poor N/A	Materials: Sectional door noted. Observations: • No deficiencies observed.	
12. Garage Door		
Good Fair Poor N/A	Observations: The garage door appeared functional during	the inspection.
13. Garage Open		
Good Fair Poor N/A	Observations:	at time of inspection.
_	s Reverse Status	
Good Fair Poor N/A	Observations: • Eye beam system present and operating.	
15. Ventilation		
Good Fair Poor N/A	Observations:  X • No Visible Ventilation noted.	
16. Vent Screens	None	and the second s
	X	
17. Cabinets		
X Poor N/A	Observations: - Appeared functional and in satisfactory cond	lition, at time of inspection.
18. Counters		
Good Fair Poor N/A	X	
Good Fair Poor N/A	X	
<u> </u>	<del></del>	

	Electrical
1. Electrical Panel	
Good Fair Poor N/A None	Location: Main Location: • North side of the house. • Exterior of structure Location: Sub Panel Location: • Located in the garage.  Observations:
	<ul> <li>No major system safety or function concerns noted at time of inspection at main panel box.</li> </ul>
2. Main Amp Breaker	1 Observations:
X	• 100 amp
3. Breakers in off pos	ition
Good Fair Poor N/A None	Observations:  • 0
4. Cable Feeds	
Good Fair Poor N/A None	Observations:  • There is an underground service lateral noted.
5. Breakers	
Good Fair Poor N/A None	Materials: Copper non-metallic sheathed cable noted.

	Roof
1. Roof Condition  Good Fair Poor N/A None  X	Materials: Common area of home owners association. • Observed from the ground with 8X56 field glasses. • Roof was visually inspected from accessible points on the interior and/or exterior. If a roof is too high, is too steep, is wet, or is composed of materials which can be damaged if walked upon, the roof is not mounted. Therefore, client is advised that this is a limited review and a licensed roofer should be contacted if a more detailed report is desired.  Materials: Asphalt shingles noted.  Observations:  • No major system safety or function concerns noted at time of inspection.
2. Flashing Good Fair Poor N/A None	
X NOTE TO THE TOTAL THE TO	Observations:  • Flashings are mastic covered, recommend re-sealing all through the roof vents and projections as a part of routine maintenance.
3. Chimney  Good Fair Poor N/A None  X	
4. Sky Lights  Good Fair Poor N/A None  X	7
5. Spark Arrestor Good Fair Poor N/A None X	 
6. Vent Caps Good Fair Poor N/A None X	
7. Gutter  Good Fair Poor N/A None	ם ק Observations:

		Observations:		
X		<ul> <li>Gutter leak noted.</li> </ul>	Potential hazard r	epairs recommended.



Gutter leak noted. Potential hazard repairs recommended.

					At	ttic		
1. A	CCES	S Poor	·. N/A	None	The Committee of the Co			
				X				

#### **Exterior Areas**

				Exterior Areas
1. Do	O <b>FS</b> Fair Poor	N/A	None	
X	an Poor		Note	Observations:  • Appeared in functional and in satisfactory condition, at time of inspection.
2. Wir	ndow C	ondi	tion	
Good F	Fair Poor	N/A_	None	Observations: • Components appeared in satisfactory condition at time of inspection.
3. Sid	ing Co	nditio	חכ	
Good F	Fair Poor	N/A	None	Materials: Composition wood siding, wood frame construction, concrete foundation.
	Ves & F	acia	None	
X	air Poor		Note	Observations:  • Eaves are the responsibility of the Home Owners Association
5. Ext	erior P	aint		
Good F	air Poor	N/A	None	Observations:  • The paint is the responsibility of the Home Owners Association
6. Stu	ICCO -			
	Fair Poor	N/A	None	Observations:  • Common areas are the responsibility of the Home Owners Association,

### Foundation

	i dandadon	
1. Slab Foundation		

Good	Fair	Poor	N/A	None	. O
		I "			Observations:
X					<ul> <li>Concrete slab not visible due to floor coverings.</li> </ul>
		1			delibrate class mot violate and to most obvoluingo

# 2. Foundation Perimeter

G000	Fair	Poor	N/A	None	
					Observations:
X					<ul> <li>No deficiencies were observed at the visible portions of the structura</li> </ul>
	<u> </u>	·			components of the home.

# 3. Foundation Walls

Good	Fair	Poor	N/A	None	Ola
					Observations:
X					<ul> <li>normal settlement</li> </ul>

# 4. Cripple Walls

Good	Fair	Poor	N/A	None
				Х

# 5 Anchor Bolts

Good	Fair	Poor	N/A	None	• • • • • • • • • • • • • • • • • • •
			Х		Observations:  • The anchor bolts were not visible.

$\sim$				_
G	ro	ur	ıa	S

1. Driveway and Walkway	Condition
-------------------------	-----------

Good	Fair	Poor	N/A	None
Х				

Materials: Asphalt driveway noted. • Concrete sidewalk noted. Observations:

- Common area maintained by association.
- Driveway in good shape for age and wear.

#### 2. Grading

Good	Fair	Poor	N/A	None
Х				

Observations:

- No major system safety or function concerns noted at time of inspection.
- Lot grading and drainage have a significant impact on the building, simply because of the direct and indirect damage that moisture can have on the foundation. It is very important, therefore, that surface runoff water be adequately diverted away from the home. Lot grading should slope away and fall a minimum of one (1) inch every foot for a distance of six (6) feet around the perimeter of the building.

# 3. Vegetation Observations

Good	Fair	Poor	N/A	None
Х				

Observations:

• No major system safety or function concerns noted at time of inspection.

Vegetation is taken care of by the Home Owners Association

#### 4. Gate Condition

Good	Fair	Poor	N/A	None
				Х

#### 5. Patio and Porch Deck

Good	Fair	Poor	N/A	None
Х				

Observations:

 Appears in satisfactory and functional condition with normal wear for its age. Appears to be sound structure.

#### 6. Stairs & Handrail

Good	Fair	Poor	N/A	None
Х				

Observations:

- Stairs and railings are maintained and are the responsibility of the Home Owners Association
- The metal railing showing areas of rust. Refinish, prime, and paint as needed.



The metal railing showing areas of rust. Refinish, prime, and paint as needed. in de la companya di la companya di Santa Maria Maria di Santa Maria di Santa di Santa di Santa di Santa di Sa

7. Gr	OHDA		actri	ഹ
7. VI	UUIIU	יו בויסו	CULI	<b>WOI</b>

Good	Ган	ruur	17/0	IACUE
X				
		i .		

Observations:

- The exterior electrical system is the responsibility of the Home Owners
- No major system safety or function concerns noted at time of inspection.

#### 8. GFCI

X	None	NVA	Poor	rair	G000
	I v				l I
	IX				l I
L I					

Observations:

- The GFCI on the exterior of the building is the responsibility of the Home Owners Association
- none visible

# 9. Main Gas Valve Condition

Good	Fair	Poor	N/A	None
Х				

Materials: exterior of structure

Observations:

 Meter located at exterior. All gas appliances have cut-off valves in line at each unit. No gas odors detected.

# 10. Plumbing

Good	Fair	Poor	N/A	None
				Ī
ΙXΙ			1	l
1 ^ 1			į .	

Materials: Copper piping noted.

Observations:

 Sewer lineDue to the age of this home I recommend a sewer line inspection. This separate inspection will show the condition of the buried sewer line from the home to the city main. Items such as tree roots, broken drain pipes, and other obstructions will be revealed. A qualified plumber with a sewer camera sewer rodding machine can inspect.

### 11. Water Pressure

Good	Fair	Poor	N/A	None	OI 11
					Observations:
X					• 60 PSI @ 9:
	Good	Good Fair	X Poor	X Fair Poor N/A	

45 A.M

### 12. Pressure Regulator

Ob	None	N/A	Poor	Fair	Good
Observations					
• none	X				

	4 33 Care	2.3	12 44 44 44	viriality in.	100	Haller Leave 2		25,500,000	46.64	200
14	022100222	_	mor	OF.		uce	12.0	$\sim$	1111	A P
113	100	1 100	LLC1	V 100	100	uuc	100	UHU	21 LL	UI I

Good	Fair	Poor	N/A	None	
					Location: Outside of garage
X	1				Observations:
L	L			<u> </u>	• Appears Functional.

## 14. Balcony

Good	Fair	Poor	N/A	None
Х				
X				

Observations:

- Is maintained by the Home Owners Association
- Appears in satisfactory and functional condition with normal wear for its age. Appears to be sound structure.

# 15. Patio Enclosure

Good	Fair	Poor	N/A	None
				X

# 16. Patio and Porch Condition

Good	Fair	Poor	N/A	None
	X			

Materials: Roofing is the responsibility of the Home Owners Association • The patio/porch roof is the same as main structure. • Asphalt shingles noted. Observations:

• Evidence of water intrusion on the starter board on the balcony area.



Evidence of water intrusion on the starter board on the balcony area.

### 17. Fence Condition

Good	Fair	Poor	N/A	None	. N.A 4 4 - 1 1 - 1 - 1 - 1 - 1
					Materials: Viny
X					· ·

### 18. Sprinklers

Good Fair

X	Х		<ul> <li>Sprinkler system is responsibility of the Home Owners Association</li> </ul>
---	---	--	---

<b>-</b>				le Hanada Banad
				ke Hazards Report
Yes	No	N/A	Don't Know	1. Is the water heater braced, strapped, or anchored to resist falling during an earthquake?
Yes	No	N/A	Don't Know	
			Х	2. Is the house anchored or bolted to the foundation?
res	No	N/A	Don't Know	If the house has cripple walls:     a. Are the exterior cripple walls braced?
res	No	N/A	Don't	]
			X	b. If the exterior foundation consists of unconnected concrete piers and posts, have they been strengthened?
'es	No	N/A	Don't Know	4. If the exterior foundation, or part of it, is made of unreinforced masonry, has
		<u></u>	<u>  X</u>	I it been strengthened?
'es	No	N/A	Don't Know	5. If the house is built on a hillside: a. Are the exterior tall foundation walls braced?
'es	No	N/A	Don't Know	
			<u> </u>	b. Were the tall posts or columns either built to resist earthquakes or have they been strengthened?
'es	No	N/A	Don't Know	] 6. If the exterior walls of the house, or part of them, are made of unreinforced
	No	N/A	Don't	masonry, have they been strengthened?
			X	7. If the house has a living area over the garage, was the wall around the garage dooropening either built to resist earthquakes or has it been
'es	No		Don't Know	strengthened?
		]	X	] 8. Is the house outside an Alquist-Priolo Earthquake Fault Zone (zones immediately surrounding known earthquake faults)?
'es	No	1	Don't Know	] 9. Is the house outside a Seismic Hazard Zone (zone identified as susceptible
		J	L X	to liquefication or landsliding)?
(EC	CUTE	D BY	<b>':</b>	
-11-	-\			(O.H.a)
elle	er)			(Seller) Date
one	or mo	re que	eipt of t estions, house	this form, completed and signed by the seller. I understand that if the seller has answered "No", or if seller has indicated a lack of knowledge, there may be one or more earthquake s.